

CUSTOMER #: 11328

15350



BIG DOG RECYCLING LLC.
KURT MOSS
22201 BURTON STREET
WEST HILLS, CA 91304
HOME: 818-470-8767 CONT: N/A
BUS: CELL:

INVOICE

UNITED TRUCK CENTERS CANOGA
8039 Canoga Avenue
Canoga Park, CA 91304
Phone (818) 710-0100 Fax (818) 710-0300
www.unitedtruckcenters.com

SERVICE ADVISOR: 403 ROSS HERMAN

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Row 1: WHITE, 08, MITSUBISHI FUSO FE18, JL6CCE1S08K000802, 8W10912, 156235/156417, 8W1091.

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: 18OCT13 DD, 08AUG16, 28SEP16, 17:00 28SEP16, 115.00, CASH, 28SEP16.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes rows for 'A TRUCK WAS TOWED IN' and 'SUBL TOWING CHARGE'.

B CUSTOMER STATES THERE IS A FUEL LEAK COMING FROM ONE OF THE FUEL LINES. CHECK AND ADVISE.

1016 diagnose fuel leak all over

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes rows for fuel leak diagnosis and repair.

UNITED TRUCK CENTERS
8039 CANOGA AVE
CANOGA PARK, CA 91304
CREDIT CARD
AMEX SALE
Card #
SEQ #:
Batch #:
INVOICE
CLERK
Approval Code:
Entry Method:
Mode:
Avs Code:
Card Code:
SALE AMOUNT \$618.65

FOUND CRACKED FUEL LINE. REMOVE CHECK ENGINE LIGHT ON. HOOKED LAP 87 FUEL RAIL PRESSURE. P0093 CRS FUEL AL CONNECTOR FLUG TO INSPECT, CLEAN THE CHECK ENGINE LIGHT OFF. PERFORM S OIL, ENGINE BELT, DRIVE LINE & U CHECK BRAKES. CHECK TIRES ALL OK AT TAL AND RUBBER.

Table with columns: DESCRIPTION, TOTALS. Includes rows for labor, parts, gas, oil, lube, sublet amount, misc charges, total charges, less insurance, sales tax.

Table with columns: DESCRIPTION, TOTALS. Includes rows for STATEMENT OF DISCLAIMER, CUSTOMER SIGNATURE, PLEASE PAY THIS AMOUNT.

Notice to Consumer: Please read important information on back. BAR # AG162215 EPA # CA0000138503

CUSTOMER #: 11328

16289



BIG DOG RECYCLING LLC.
KURT MOSS
22201 BURTON STREET
WEST HILLS, CA 91304
HOME:818-470-8767 CONT:N/A
BUS: CELL:

INVOICE

UNITED TRUCK CENTERS CANOGA
8039 Canoga Avenue
Canoga Park, CA 91304
Phone (818) 710-0100 Fax (818) 710-0300
www.unitedtruckcenters.com

PAGE 1

SERVICE ADVISOR: 403 ROSS HERMAN

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Includes details for a white Mitsubishi Fuso FE18 truck with VIN JL6CCE1S08K000802.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists repair items such as 'INSTALL NEW FUEL RAIL BRACKET' and 'REPLACE FUEL LINE BRACKET'.

FC:
158746 REMOVED INTAKE COOLER HOSES FOR ACCESS. REMOVED INTAKE THROTTLE BODY COMPONENTS FOR ACCESS TO THE FUEL TUBE BRACKET. INSTALLED NEW BRACKET. INSTALLED NEW FUEL LINE (NEW LINE COVERED UNDER WARRANTY.) REASSEMBLED ALL. RAN AT HIGH IDLE. NO LEAKS PRESENT. ROAD TESTED. ALL GOOD AT THIS TIME.

Service Invoice

Table with columns: DESCRIPTION, TOTALS. Includes sections for 'ON BEHALF OF SERVICING DEALER', 'STATEMENT OF DISCLAIMER', and a summary of charges totaling 704.09.

Notice to Consumer: Please read important information on back.

BAR # AG162215

EPA # CA0000138503



Auto Care Experts

www.americantiredepot.com

American Tire Depot - SFS 911
14100 Rosecrans Ave
SANTA FE SPGS, CA 90670
(562)921-8372

23

Customer ID: 0911003782
Name: ETC BUILDING DESIN
Address: 12603 ALLARD ST
Address 2:
City, State, Zip Code: SANTA FE SPGS, CA, 90670
Home Phone: (909) 908-4138
Work Phone: (909) -
Other Phone: () -
Fax Exempt #:

Year: 07
Make: MITSUBISHI
Model: FUSO
Lic No: 8W10912
VIN:
Color:
Engine: L4-2378cc 2.4L
Mileage In: 159090
Mileage Out: 159090

Create Date: 02/09/17 13:11:14
Date/Time: 02/09/17 14:56:58
Work Order #: 14399
Invoice #: 911007521
Email Address: albertlopez961@yahoo.com
PO Number:
Fleet/Wholesale: N
EPA #: CAL000313233
BAR #: AK185897

Salesperson: A. Lopez
Service comments:

REPLACE 2 FRONT AND 2 REAR MOVE LR TIRES TO BOTH INSIDE
TIRE PRESSURE: LF 32 RF 32 LR 32 RR 32 SPARE 32
TREAD DEPTH: LF 11/32 RF 11/32 LR 11/32 RR 11/32 SPARE 11/32
BRAKE PAD THICKNESS: LF __ RF __ LR __ RR __

REVISED ESTIMATE AUTHORIZATION(S):

APPROVED BY: CONTACT: ETC BUILDING DESIN ADD. AMT: 915.82
DATE: 02-09-17 TIME: 1:12 PM PREVIOUS EST: 0.00 REV. EST: 915.82
Work Authorized: four tires

APPROVED BY: CONTACT: ETC BUILDING DESIN ADD. AMT: 367.96
DATE: 02-09-17 TIME: 1:39 PM PREVIOUS EST: 915.82 REV. EST: 1283.78
Work Authorized: 6 tires

Table with columns: Part #, RFR, Loc, Description, Parts, Labor, Total. Includes items like MOUNT & BALANCE TIRE, VALVE STEM & WHEEL WEIGHTS, CALIFORNIA TIRE RECYCLE FEE, TIRE DISPOSAL FEE, americus 215/75r17.5 16ply, FET on part *amd9001.

Customer Wishes To Discard Old Parts ***

EDIT CARD #: XXXX-XXXX-XXXX-3006
PROVAL # : 280614
KET # :

Customer Signature: [Handwritten Signature]

Thank you for your business. PAY AMEX AMOUNT 1,283.78
PARTS TOTAL 1,025.64
SALES TAX 82.94
LABOR TOTAL 175.20
GRAND TOTAL 1,283.78
ALL PARTS ARE NEW UNLESS OTHERWISE SPECIFIED. TECH: 001118-0.00 Gerardo

CUSTOMER #: 389929


24

61557



Since 1949

INVOICE



P.O. Box 88 Santa Ana, CA 92702
936 E. 3rd. St. Santa Ana, CA 92701
(714) 338-6030

ETC BUILDING & DESIGN
12603 ALLARD ST
SANTA FE SPRINGS, CA
HOME: 909-908-4138 CONT: 909-908-4138

PAGE 1

BUS: CELL: SERVICE ADVISOR: 700 ORLANDO 'OJ' MANRIQUE

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP, PROMISED, PO NO, RATE, PAYMENT, INV. DATE

R.O. OPENED: READY: OPTIONS: ENG: C85369

09:30 16FEB17 14:46 28FEB17

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL

A CHANGE ENGINE OIL AND FILTER(S), LUBE CHASSIS
CAUSE: CUSTOMER REQUEST TO PERFORM LOF
LOF CHANGE ENGINE OIL AND FILTER(S), LUBE CHASSIS
226CFUSO 75.00 75.00
H100 HAZARDOUS HANDLING FEE 8.00 8.00
1 QY010012 FVP, OIL FILTER, 4M50, 33.83 30.36 30.36
1 MD050317 **GASKET, OIL DRAIN, 1 3.83 3.83 3.83
3 S1019 15W40 GALLON 36.76 21.50 64.50
1 2-9004Q-608-0 DELO GREASE EP 10.08 10.08 10.08
1 248 248 MDP 18.20 18.20 18.20

PARTS: 126.97 LABOR: 75.00 OTHER: 8.00 TOTAL LINE A: 209.97

PERFORM LUBE AND CHANGE OIL AND FILTER.

B C/S REAR HAZARD LIGHTS INOP

8 ELECTRICAL
226CFUSO 895.00 895.00
1 48000 CONVERTER, TAIL LAMP 123.16 96.71 96.71
30 056112 16-14 HEATLESS BUTT CON 1.12 0.86 25.80
1 BD-7376 15 AMP MINI FUSE 0.70 0.70 0.70
1 45742 45 SERIES MODULE W/T/S- LH 87.49 57.21 57.21
1 45743 45 SERIES MODULE W/T/S- RH 87.49 57.21 57.21
12 23426 PRIMARY WIRE VINYL 16GA RED 100FT 0.64 0.64 7.68
1 BD-7506 TAPE ELECTRIC 3/4IN X66FT 4.84 4.84 4.84
1 9421777 (S) BULB 4.11 4.11 4.11

PARTS: 254.26 LABOR: 895.00 OTHER: 0.00 TOTAL LINE B: 1149.26

FOUND LIGHTS ARE NOT POSSIBLE FOR REPAIR DUE TO THE TYPE OF LIGHTS
THEY ARE AND WIRING DO NOT MATCH REPLACED LIGHTS DRILLED OUT NEW HOLES
AND REPAIRED HARNESS TESTED ALL OK AT THIS TIME

C PERFORM TIRE PRESSURE INSPECTION SET ALL TIRE PRESSURES TO

MANUFACTURER SPECIFICATIONS,
CTP PERFORM TIRE PRESSURE INSPECTION SET ALL TIRE
PRESSURES TO MANUFACTURER SPECIFICATIONS,

226 CP 0.00 0.00

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items.

Table with columns: DESCRIPTION, TOTALS. Rows include LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, SERVICE HISTORY FEE, TOTAL CHARGES, LESS DISCOUNT, SALES TAX, PLEASE PAY THIS AMOUNT

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

CUSTOMER SIGNATURE

BAR # ARD106255

EPA # CAD983581497
CAL000021081

CUSTOMER #: 389929

61557




Since 1949

ETC BUILDING & DESIGN
12603 ALLARD ST
SANTA FE SPRINGS, CA
HOME: 909-908-4138 CONT: 909-908-4138
BUS: CELL:

INVOICE

PAGE 2



P.O. Box 88 Santa Ana, CA 92702
936 E. 3rd. St. Santa Ana, CA 92701
(714) 338-6030

SERVICE ADVISOR: 700 ORLANDO 'OJ' MANRIQUE

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO. NO., RATE, PAYMENT, INV. DATE. Includes details for 08 MITSUBISHI FE, VIN JL6CCE1S08K000802, license 8W10912, and service dates.

Table with columns: LINE OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00

OVER 10,000 GVW. CHECKED AND ADJUSTED AIR PRESSURES TO MANUFACTURER SPECIFICATIONS IN THIS ORDER: LF, RF, LR, RR

D PERFORM COMPLIMENTARY TWENTY TWO POINT VEHICLE INSPECTION AND COMPLETE ATTACHED FORM.

22 PERFORM COMPLIMENTARY TWENTY TWO POINT VEHICLE INSPECTION AND COMPLETE ATTACHED FORM.
226 CP 0.00 0.00 0.00 TOTAL LINE D: 0.00
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00

E** INSTALL TOM'S TRUCK CENTER MUD FLAPS AND LICENSE PLATE FRAMES. CAUSE: PER CUSTOMER REQUEST
MUDFLAPS INSTALL TOM'S TRUCK CENTER MUD FLAPS AND LICENSE PLATE FRAMES.

226 IMF (N/C)
2 24X30P PLASTIC FLAP (N/C)
PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE E: 0.00
INSTALLED TOMS FLAPS

F** REPLACE BELTS 12 ENGINE
226CFUSO 150.00 150.00
1 QY010006 FVP, FAN BELT, EG8, W/A 48.07 43.14 43.14
PARTS: 43.14 LABOR: 150.00 OTHER: 0.00 TOTAL LINE F: 193.14
REPLACED BELT

G** PERFORM BG DEALER RECOMMENDED POWER STEERING SERVICE CAUSE: PER CUSTOMER REQUEST DUE TO TIME OR MILEAGE
PSF PERFORM BG DEALER RECOMMENDED POWER STEERING SERVICE

Table with columns: Description, Amount, Total. Includes 226CFUSO 150.00 150.00, H300 HAZ MAT FEE 3.00 3.00, 1 6700R POWER STEERING SERVICE 59.94 59.94

Table with columns: Description, Labor Amount, Parts Amount, Gas, Oil, Lube, Sublet Amount, Service History Fee, Total Charges, Less Discount, Sales Tax, Please Pay This Amount. Includes ON BEHALF OF SERVICING DEALER... STATEMENT OF DISCLAIMER

CUSTOMER #: 389929

61557




Since 1949

ETC BUILDING & DESIGN
12603 ALLARD ST
SANTA FE SPRINGS, CA
HOME: 909-908-4138 CONT: 909-908-4138
BUS: CELL:

INVOICE

PAGE 3



P.O. Box 88 Santa Ana, CA 92702
936 E. 3rd. St. Santa Ana, CA 92701
(714) 338-6030

SERVICE ADVISOR: 700 ORLANDO 'OJ' MANRIQUE

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO. NO., RATE, PAYMENT, INV. DATE. Includes data for 08 MITSUBISHI FE, VIN JL6CCE1S08K000802, license 8W10912, mileage 159484/159498, tag T7838.

Table with columns: R.O. OPENED, READY, OPTIONS, ENG: C85369. Includes times 09:30 16FEB17 and 14:46 28FEB17.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Includes PARTS: 59.94 LABOR: 150.00 OTHER: 3.00 TOTAL LINE G: 212.94.

PERFORMED BG POWER STEERING SYSTEM SERVICE.

H** PERFORM BG DEALER RECOMMENDED TRANSMISSION FLUID EXCHANGE HEAVY

DUTY. REPLACE THE TRANSMISSION IN LINE FILTER IF EQUIPPED.

CAUSE: PER CUSTOMER REQUEST DUE TO TIME OR MILEAGE

TFHDTY PERFORM BG DEALER RECOMMENDED TRANSMISSION

FLUID EXCHANGE HEAVY DUTY. REPLACE THE

TRANSMISSION IN LINE FILTER IF EQUIPPED.

226CFUSO 300.00 300.00

H300 HAZ MAT FEE 3.00 3.00

1 6602 TRANS SERVICE KIT 95.91 95.91 95.91

16 112610 ATF QT 10.97 7.17 114.72

PARTS: 210.63 LABOR: 300.00 OTHER: 3.00 TOTAL LINE H: 513.63

PERFORMED COMPLETE TRANSMISSION FLUSH WITH FRESH FLUID AND BG

PRODUCTS.

I** * PNEUMATIC CLEANING OF DPF AND BAKE PROCESS IF NECESSARY

DPF * PNEUMATIC CLEANING OF DPF AND BAKE PROCESS

IF NECESSARY

226 CDPF 850.00 850.00

2 ME193825 GASKET, DPF, FE8, 08-10 31.80 28.56 57.12

1 ME226298 EXH BRAKE, FE8, 08-10 595.74 412.43 412.43

2 ME416753 **GASKET, EXH PIPE, FE 17.63 16.13 32.26

PARTS: 501.81 LABOR: 850.00 OTHER: 0.00 TOTAL LINE I: 1351.81

BAKE

SERVICED DPF. PNEUMATIC AND THERMAL REGENERATION REQUIRED.

RESTRICTION BEFORE: 5.4 RESTRICTION AFTER CLEANING: 3.8

J** ADJUST VALVES

12 ENGINE

226CFUSO 893.00 893.00

1 ME222553 **GASKET, ROCKER COVE 42.95 38.57 38.57

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN.

STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items.

DESCRIPTION TOTALS

LABOR AMOUNT

PARTS AMOUNT

GAS, OIL, LUBE

SUBLET AMOUNT

SERVICE HISTORY FEE

TOTAL CHARGES

LESS DISCOUNT

SALES TAX

PLEASE PAY THIS AMOUNT

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE) CUSTOMER SIGNATURE

BAR # ARD106255

EPA # CAD983581497

CAL000021081

CUSTOMER #: 389929

61557




Since 1949

ETC BUILDING & DESIGN
12603 ALLARD ST
SANTA FE SPRINGS, CA
HOME: 909-908-4138 CONT: 909-908-4138
BUS: CELL:

INVOICE

PAGE 4



P.O. Box 88 Santa Ana, CA 92702
936 E. 3rd. St. Santa Ana, CA 92701
(714) 338-6030

SERVICE ADVISOR: 700 ORLANDO '0J' MANRIQUE

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO. NO., RATE, PAYMENT, INV. DATE. Includes values like 08 MITSUBISHI FE, VIN JL6CCE1S08K000802, LICENSE 8W10912, MILEAGE 159484/159498, TAG T7838.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Lists parts like GASKET, ROCKER CASE, O-RING, INJECTOR, ADHESIVE with prices.

PARTS: 213.90 LABOR: 893.00 OTHER: 0.00 TOTAL LINE J: 1106.90
PERFORMED VALVE ADJUST REPLACED GASKETS TEST DROVE PERFORMED MANUAL
REGEN FOUND EXHAUST BRAKE NOT OPERATIONAL REPLACED EXHAUST BRAKE TEST
DROVE PERFORMED MANUAL REGEN ALL OK AT THIS TIME

EST: 600.00 16FEB17 09:30 SA: 700
CONTACT: MICH (305) 801-6016
LOP LIGHTS PSF DPF TFHDTY BELT V/A

EST: 4,500.00 20FEB17 13:22 SA: 700
CONTACT: MICH (305) 801-6016
SVC & REPAIRS ADDITIONAL EXH BRAKE & LAMPS

EST: 5,500.00 24FEB17 10:35 SA: 700
CONTACT: MICH (305) 801-6016
REC////////'D AUTH 2-20-17
10:30 MICH/2-23-17 CALLED
LEFT MESSAGE. 2-24-17 REC AUTH
FOR ADDITIONAL REPAIRS.

43939059888
TOM'S TRUCK CENTER
1008 E 4TH ST.
SANTA ANA, CA 92701
714-560-4100

Term ID: 003 Ref #: 006
Shift #: 2

Sale

XXXXXXXXXX3066
AMEX Entry Method: Manual
02/28/17 15:33:18
Inv #: 000006 Appr Code: 180620
Apprvd: Online Batch#: 000632
Cust Ref #: 61557
Total: \$ 4,846.98

Customer Copy
THANK YOU!

ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

Table with columns: DESCR, LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, SERVICE HISTORY FEE, TOTAL CHARGES, LESS DISCOUNT, SALES TAX, PLEASE PAY THIS AMOUNT. Values include 3313.00, 1410.65, 0.00, 0.00, 14.00, 4737.65, 0.00, 109.33, 4846.98.

(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE) CUSTOMER SIGNATURE

BAR # ARD106255 EPA # CAD983581497 CAL000021081

Rods Truck Repair, Inc.

11910 Greenstone Avenue
Santa Fe Springs, CA 90670

800-559-1778/562-946-2808

Fax: 562-946-2848

E-Mail:

rodstruckrepair@gmail.com

Invoice

DATE	Invoice #
3/28/2017	25767

ETC BUILDING & DESIGN

P.O. No.	Terms	Unit No.	License No.	Mileage
		FUSO FE180	8W10912	160144

Description	Qty.	Amount
AS PER ESTIMATE, CHECK FRONT END & REPORT, P/U PARTS AND R&R DRAGLINK & CHECK 3-AXLE ALIGNMENT.		
PARTS- DRAGLINK - MK382603	1	367.77T
OTHER CHARGES: Freight	1	35.00
LABOR- LABOR RATE \$95 PER HOUR	4.75	451.25
*** NOTE: OPEN ITEM - 3-AXLE ALIGNMENT.		

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE IN SHOP WITH THE NECESSARY MATERIALS. You & your employees may operate the vehicle for the purpose of testing, inspection, & delivery at my risk. An express mechanics lien is acknowledged on said vehicle to secure the amount of the repairs, thereto. You will not be responsible for the loss of any articles left in the vehicle in case of fire, theft or accident to the vehicle, or any other cause beyond your control.

SIGNED: _____
..... (Cash required unless prior agreements are made to authorization.)

Subtotal	\$854.02
Sales Tax	\$32.18
Total	\$886.20

Rods Truck Repair, Inc.

11910 Greenstone Avenue
 Santa Fe Springs, CA 90670

800-559-1778/562-946-2808

Fax: 562-946-2848

E-Mail:

rodstruckrepair@gmail.com

Invoice

DATE	Invoice #
8/08/2017	26441

ETC BUILDING & DESIGN

P.O. No.	Terms	Unit No.	License No.	Mileage
		FUSO/MITSUBISHI	8W10912	160546

Description	Qty.	Amount
INSPECT TRUCK & REPLACE (1) RED LENS ON R/TOP REAR SIDE, CHANGE OIL, FILTERS, LUBE, CHECK LITES, BRAKES, TIRES & ADJ PRESSURE, HAD TO REMOVE FUEL FILTER HSG TO R&R FUEL FILTER & REINSTALL, START & CHECK FOR LEAKS. HOOK UP LAPTOP & CHECK CODES & COULD NOT CLEAR CODE P1421 NEED PASSWORD FROM MANUFACTURER.		
PARTS-		
LENS, RED - 91572-3	1	1.24T
OIL FILTER - ME228898	1	36.15T
FUEL FILTER - ME222135	1	30.75T
AIR FILTER - ME423319	1	83.69T
ENVIRONMENTAL FEE:	1	15.00
LABOR-		
LABOR RATE \$95 PER HOUR	3.75	356.25

I HEREBY AUTHORIZE THE REPAIR WORK TO BE DONE IN SHOP WITH THE NECESSARY MATERIALS. You & your employees may operate the vehicle for the purpose of testing, inspection, & delivery at my risk. An empress mechanics lien is acknowledged on said vehicle to secure the amount of the repairs, thereto,. You will not be responsible for the loss of any articles left in the vehicle in case of fire, theft or accident to the vehicle, or any other cause beyond your control.

SIGNED: _____
 (Cash required unless prior agreements are made to authorization.)

Subtotal	\$523.08
Sales Tax (8.75%)	\$13.29
Total	\$536.37