



# lease return

## report.

---

- **Lessee:**
- **Lessor:** US BANK
- **Lease Agreement/Contract #:** 522-0021687-000
- **Return Date:**
- **Equipment Description:** Stratasys J55 3D Printer
- **Model:** J55
- **Serial Number:** J5500532
- **Current Hour/Meter Reading:** 935 Print Hours

### Condition Assessment

- Excellent  Good  Fair  Poor
- **Functional Check:**  Working  Not Working
- **Significant Damage/Missing Parts:** None

### Inspection Notes

Printer was inspected 3/4/2026 by Stratasys certified technician Jason Brown.

- Printer exterior is in excellent condition
- All notifications and calibrations are up to date
- Software updated
- Wiper - good
- Roller Bath – good
- Vacuum – good
- Printing Heads acceptable condition for the age
- Test Print – good
- All systems are operational
- See pictures in the Exhibit A

### Signatures

- **Lessee Representative:** \_\_\_\_\_ **Date:** \_\_\_\_\_



PURPLE PLATYPUS

ADVANCED 3D SOLUTIONS

- **Inspector Representative:** Maksym Semko Digitally signed by Maksym Semko  
DN: cn=Maksym Semko, o=Purple Platypus, ou=Engineering, email=semko@purpleplatypus.com, c=US  
Date: 2020.03.10 14:49:40 -0700 **Date:** 3/10/2026



PURPLE PLATYPUS

ADVANCED 3D SOLUTIONS

## Exhibit A





PURPLE PLATYPUS

ADVANCED 3D SOLUTIONS





PURPLE PLATYPUS

ADVANCED 3D SOLUTIONS





PURPLE PLATYPUS

ADVANCED 3D SOLUTIONS

